

**PRODUCT SUPPORT BULLETIN** **No.0202**

**PRODUCT:** TSE Rockbreaker Systems

May 25, 1999

**SUBJECT:** Danfoss Control Valve Design Change

**EQUIPMENT AFFECTED:**

- CLASSIFICATION:**
- Mandatory Safety
  - Mandatory Repair
  - Optional Repair
  - Fix-as-fail
  - Information

**SITUATION:** Danfoss has redesigned the anti-shock valves in their PVG32 control valves to allow for a higher flow rate.

**SOLUTION:** To accomplish this, Danfoss increased the size of the shock valve and the valve body cavity that it fits into.

The design change has created new part numbers for these parts and although the complete valve body assembly is interchangeable with the previous assembly, the new shock valves will not fit into the old body design.

It is necessary to determine which valve assembly the customer actually has before supplying either a replacement valve body or shock valves.

This change applies to all rockbreaker systems supplied after May 15, 1998.