

## PRODUCT SUPPORT BULLETIN #215

**PRODUCT:** TC 151S Compactors

Sep. 20, 2001

**SUBJECT:** Swivel Pin Weld

**EQUIPMENT AFFECTED:** Sin's 2000045, 2000046, 2000047, 2000086, 2000087, 2000128, 2001023, 2001024

**CLASSIFICATION:** Mandatory Safety  
Mandatory Repair  
Optional Repair  
Fix-as-fail  
Information

**SITUATION:** Product alert, inspect the weld on the bottom side of the swivel boss. If there are any visible cracks on the weld or if the weld is concave, repairs are required.

**PROGRAM INSTRUCTIONS:** If repairs are required please refer to service bulletin #214.

