

PRODUCT SUPPORT BULLETIN #217

PRODUCT: TC 301 Compactors

Oct. 5, 2001

SUBJECT: Vibration isolator mounts

EQUIPMENT AFFECTED: S/N: 2000068-1,-2,-3,-4,-5,-6,-7,-8 2000070-1,-2,-3,-4,-5,-6 2000088-1,-2,-3

CLASSIFICATION: Mandatory Safety
Mandatory Repair
Optional Repair
Fix-as-fail
Information

SITUATION: There has been a change to the rubber structure.

SOLUTION: All four isolators must be replaced as aset. The isolators are solid and do not have a hole through the centre.

PROGRAM INSTRUCTIONS: Order part number 1007828 at a quantity of 4. Do not mix the new isolators with the previous ones. Submit a completed warranty claim form with the unit serial number and return the removed isolators, for credit.



Old Style Lattice Mount



New Style Lattice Mount #1007828