



CIRCULATE TO:
Parts Manager:
Sales Manager:
Service Manager:
Maintenance Manager:

PRODUCT SUPPORT BULLETIN #0222

Product: Automatic Grease Systems

Subject: Lincoln Automatic Grease System

Equipment Affected: BTI Boom Systems

For Your Information

Situation: The Series Progressive Lincoln System will stop working in the case of one grease nozzle malfunctions. One grease nozzle may stop working if it becomes plugged from contamination in which case the complete system will stop.

Solution: The Lincoln Centromatic System is available as a direct replacement. If one grease nozzle does malfunction on this system, only that point does not receive grease but the rest of the system remains operational and supplies grease to the other points.

Program Instructions: The new Centromatic Grease Systems Kits may be purchased to replace the systems on the existing units.

New Boom Systems will have the new Automatic Systems installed unless otherwise specified.

For additional information, please contact BTI Customer Service.